

---

Subject: Re: New Computer Research

Posted by [kopaka649](#) on Fri, 16 Jun 2006 00:00:59 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Unfortunately, the creative cards tend to be a bitch on some motherboards. For example, my friend got an Audigy 2 ZS and got the squeal of death. Then he tried getting an X-fi and he still has the problem. Strangely, the only way to fix it is to go into the BIOS and then exit on every boot.

---