Subject: Re: MP3 Player buying advice Posted by EvilWhiteDragon on Mon, 15 Feb 2010 13:43:24 GMT View Forum Message <> Reply to Message

CarrierII wrote on Mon, 15 February 2010 14:32EvilWhiteDragon wrote on Mon, 15 February 2010 12:31Can't you just solder on the battery connector again? Sounds like an easy fix tbh.

Connections are too close to each other, there's no way my soldering iron wouldn't solder all three of them to each other.

You could try it anyway? It's not like it's working now right?