
Subject: CD-RW Drive read as a CD-ROM Drive
Posted by [exnyte](#) on Wed, 15 Oct 2003 19:02:01 GMT
[View Forum Message](#) <> [Reply to Message](#)

da_shizIt works just fine...so i'm figuring it's the os. the connection is USB 2.0 but it also says it works w/o 2.0.

98se has some problems with USB support. (in fact, Microsoft claims they there is no, and never will be USB support for 98se.) Here's a few places you might be able to start to get it working?

Win98 SE USB

Microsoft Windows 98SE - USB Devices May Not Work 4.10.2223
